



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Monday, December 7, 2020	Project Contact:	Brian Clauto		
Spread H: Montgomery	ST12180+00-12199+50 ST12117, ST12102+05-12098+50 ATWS 703, 704A, 1446, 1375 AR MN270.01, 274, 275	Weather:	Wet		

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
☐ Tree Felling		☐ Clearing/Grubbin			Grading		Trenching		Stringing/Welding			
	Lowering/l	wering/Backfilling Final Grading Temp. Stabilization Perm.		Perm. Stabilization	\boxtimes	Dor	mant					
									Yes	No	N/A	
	1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes			
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						\boxtimes				
	3.	Areas of o	fsite	sediment deposition o	bserve	ed?				\boxtimes		
 <u>Comments:</u> Inspected the following resources: S-C21, S-0011,S-MM11, S-MM13, S-EF31 ECD's were in place and functioning at the designated crossings. 												
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (24-Hour Deadline from Notification) - N/A												
Recommended Corrective Action: N/A												

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Monday, December 7, 2020



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, December 7, 2020

Figure 1: Designated crossing S-MM13, ECD's are in place



Figure 2: Designated crossing S-MM11, ECD's are in place



Figure 3: ST12180+00 area is stabilized



Figure 4: Near ST12117+00 temporary/permanent waterbars are in place and functioning.

